



QtPro Firmware Field Updating: Version 6.7.1

Please read prior to attempting to update!

- Version 6.7.1 of the Qt300/600 controller firmware is the latest version. Update is optional. The full list of changes can be found in the Release Notes.
- Any Qt300/600 controller unit may be updated to version 6.7.1 if the controller meets the following requirements:
- The firmware version must be 5.0.0 or newer, the hardware version must be 2 or newer, and the bootloader version must be 2 or newer.
- The version numbers can be determined as indicated below. If any of the three version numbers is older than the above values, **please contact Tech Support.**

Viewing Version Number

- On the LCD screen, the version of firmware is shown when the controller is turned on. It will be displayed as a three-part numerical value (i.e. 5.0.0, or 6.3.0). Alternatively, it may be found by cycling forward or backwards through the screen modes. (It appears after the final Zone of "Input B.") The same screen also shows "HxBy" where x and y are numeric values. Please record these as versions of hardware and bootloader along with the firmware version. As stated above, if the values of x or y are less than 2, **please contact tech support.**